

Fluid Tip Metric Conversion

Standard Tip Sizes

0.50 MM	=	0.021		GF Dyes, Stains	
0.7 MM	=	0.028			
0.9 MM	=	0.036		GF Stains, Clears	
1.1 MM	=	0.043			
1.3 MM	=	0.051		GF Whites, Clears	
1.5 MM	=	0.061			
1.8 MM	=	0.072		Latex Paints	
2.0 MM	=	0.084			
3.0 MM	=	0.110			

FUJI SPRAY TIPS SIZES

2H	.7mm	0.025		Dyes ,Stains	
3H	1mm	0.039		Enduro Topcoats	
4H	1.4mm	0.055		White Poly, Undercoat	
6H	2.2mm	0.086		Milk Paints	

APOLLO SPRAYER TIP SIZES

#1	.75mm	0.0295		Dyes ,Stains	
#2	1.0mm	0.039		Enduro Topcoats	
#3	1.5mm	0.059		White Poly, Undercoat	
#4	2.0mm	0.079		Milk Paints	
#5	2.5mm	0.098			

Air Assited Airless

	Pump PSI		Assit Air		Tip Size
Clears	600 psi		20-25 psi		0.011
Primers	1400 psi		40 psi		0.013
Pigmented Poly	1150 psi		20 psi		0.011
Milk Paint	1400 psi		40 psi		0.013